

From:

Full Force Heating & Cooling 459 Main Street Suite 101, Box 379 Trussville, AL 35173 brandon@fullforcehvac.com

Т	_	
	U	

Brandon Brown
25 Polo Lane
Odenville, AL 35120
brandon@sunrise-marketing.com

-	Surrounding Areas
Licensed & Insured	Financing
Free Estimates	Available
Installation	Residential •
Maintenance	Commercial
Repairs	
Heating & Co	ooling



Total Due	\$0.00
Due Date	April 20, 2023
Invoice Date	April 20, 2023
Invoice Number	INV-0002



Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
1	Install all ceiling grills - (6) 6x14 (3) 6x10 (2) 4x8	\$10.00	0%	\$10.00
1	4x8 ceiling boot for bathroom	\$0.00	0%	\$0.00
1	6x10 ceiling boot for sunroom	\$0.00	0%	\$0.00
1	6x10 ceiling boot for kitchen	\$0.00	0%	\$0.00
1	24x24 return grill w/ filter	\$0.00	0%	\$0.00
1	30x30 drain pan to go under unit in attic With auxiliary safety switch, and an additional safety switch inside the primary drain of the PVC line. So two forms of safety, a primary and secondary in case one fails.	\$0.00	0%	\$0.00
1	6" duct board collar	\$0.00	0%	\$0.00
2	6" R6 Flex	\$0.00	0%	\$0.00
1	8" R6 Flex	\$0.00	0.00%	\$0.00

Total Due	\$0.00
Paid	-\$10.00
Tax	\$0.00
Sub Total	\$10.00

The above will also include duct modifications to help balance air, tape and duct sealant any loose connections. Some ducts will need to be reinsulated in parts to prevent condensation from dripping moisture at ceiling register. Return plenum in ceiling will be framed in better, and taped and sealed to prevent any attic air being sucked into return. Will also perform maintenance on system, chemical wash coils, inspect blower, and test system function and pressures. Also secure ductwork from falling in future.

Payment is due upon receipt.